

## Tyco Electronics Substance Report

Kumar, Shashi

Dec 19, 2008

The below information is provided based on reasonable inquiry of our suppliers and represents our current actual knowledge based on the information provided by our suppliers. This information is subject to change. This information does not in any way modify existing purchase specifications or existing contractual or other agreement terms between Tyco Electronics Corporation (or its affiliated companies) and its customers.

### General Properties

<b>Part Name</b>	02P MTA156 HDR ASSY SQ R/A
<b>Part Number</b>	640387-2
<b>Total Part Weight (g)</b>	0.794481
<b>Unit of Measure</b>	EA (each)

### REPORTED CONTENT

<b>Name</b>	<b>CAS Number</b>	<b>Weight (g)</b>	<b>Weight (%)</b>
Cadmium	7440-43-9	0.000053	0.006661
Chromium	7440-47-3	0.000005	0.000666
Unspecified Compliant Substance	Unspecified Compliant Substance	0.244566	30.783146
Nickel	7440-02-0	0.003501	0.440637
Mercury	7439-97-6	0.000003	0.000333
Iron	7439-89-6	0.000265	0.033305
Tin	7440-31-5	0.004016	0.505549
Cobalt	7440-48-4	0.000529	0.066611
Copper	7440-50-8	0.378385	47.626756
Contains No Reportable TE5081-2 Substances	TE5081-2-0506	0.000005	0.000617
Beryllium	7440-41-7	0.000005	0.000666
zinc	7440-66-6	0.148166	18.649372
Arsenic	7440-38-2	0.000053	0.006661
Manganese	7439-96-5	0.000265	0.033305
Antimony oxide	1309-64-4	0.014234	1.791612
Lead	7439-92-1	0.000377	0.047441
Antimony	7440-36-0	0.000053	0.006661
<b>All (17 items)</b>			
Total		0.794481	