

Tyco Electronics Substance Report

DG, MANJUNATH
Dec 12, 2008

The below information is provided based on reasonable inquiry of our suppliers and represents our current actual knowledge based on the information provided by our suppliers. This information is subject to change. This information does not in any way modify existing purchase specifications or existing contractual or other agreement terms between Tyco Electronics Corporation (or its affiliated companies) and its customers.

General Properties

Part Name	02P MTA156 HDR ASSY FL/ST 15AU
Part Number	641119-2
Total Part Weight (g)	0.644679
Unit of Measure	EA (each)

REPORTED CONTENT

Name	CAS Number	Weight (g)	Weight (%)
Beryllium	7440-41-7	0.000004	0.000593
Gold	7440-57-5	0.000560	0.086917
Contains No Reportable TE5081-2 Substances	TE5081-2-0506	0.000003	0.000530
Chromium	7440-47-3	0.000004	0.000593
Manganese	7439-96-5	0.000191	0.029643
Copper	7440-50-8	0.273280	42.389915
Cobalt	7440-48-4	0.000382	0.059287
Cadmium	7440-43-9	0.000038	0.005929
Lead	7439-92-1	0.000367	0.056945
Iron	7439-89-6	0.000191	0.029643
Arsenic	7440-38-2	0.000038	0.005929
Nickel	7440-02-0	0.002467	0.382715
Antimony	7440-36-0	0.000038	0.005929
Tin	7440-31-5	0.001290	0.200154
Mercury	7439-97-6	0.000002	0.000296
zinc	7440-66-6	0.107009	16.598764
Unspecified Compliant Substance	Unspecified Compliant Substance	0.244581	37.938308
Antimony oxide	1309-64-4	0.014234	2.207910
All (18 items)			
Total		0.644679	