



## Basic features

<b>Principle of operation</b>	Clamp holder
<b>Scope of delivery</b>	Clamp holder (1x) Nut ISO 4032-M3 Screw ISO 4762-M3x8
<b>Use</b>	for sensors Ø8 mm For M08 sensors
<b>Version</b>	Mounting block

## Material

<b>Material</b>	PA 6
-----------------	------

## Mechanical data

<b>Dimension</b>	16 x 12 x 20 mm
<b>Mounting part</b>	Screws, clamps
<b>Tightening torque clamping screw</b>	1.1 Nm