



## Basic features

Principle of operation	General installation accessories
Use	For M18 sensors

## Environmental conditions

Ambient temperature	-30...85 °C
---------------------	-------------

## Material

Material	PA
----------	----

## Mechanical data

Tightening torque max.	2 Nm
------------------------	------