

WIRE DRESS COVER	DESCRIPTION
2272162-[-]	4-Position Straight Exit
2272163-[-]	4-Position Right-Angle Exit
2272164-[-]	3-Position Straight Exit
2272165-[-]	3-Position Right-Angle Exit
2272168-[-]	2-Position Straight Exit
2272169-[-]	2-Position Right-Angle Exit




Figure 1

1. INSTALLATION

1. Place either pocket of the wire dress cover onto the rear flange of the connector housing and form the wire bundle under the other pocket and centered in the wire exit. See Figure 2, Detail A.
2. Fold the wire dress cover at the center of the hinge so that the halves mate around the connector housing; then ensuring that the wire bundle is within the seams of the wire exit, compress the halves together until all of the latches are secure. See Figure 2, Detail B.




Figure 2

2. REMOVAL

Using the tip of a small screwdriver, flex the latches, then rotate the halves apart. Refer to Figure 3.



Figure 3

3. REVISION SUMMARY

Initial release of instruction sheet