

## Tyco Electronics Substance Report

Kumar, Shashi  
Dec 18, 2008

The below information is provided based on reasonable inquiry of our suppliers and represents our current actual knowledge based on the information provided by our suppliers. This information is subject to change. This information does not in any way modify existing purchase specifications or existing contractual or other agreement terms between Tyco Electronics Corporation (or its affiliated companies) and its customers.

### General Properties

<b>Part Name</b>	03P MTA156 HDR FLRA FB 30AU LF
<b>Part Number</b>	3-641210-3
<b>Total Part Weight (g)</b>	1.254299
<b>Unit of Measure</b>	EA (each)

### REPORTED CONTENT

<b>Name</b>	<b>CAS Number</b>	<b>Weight (g)</b>	<b>Weight (%)</b>
Antimony	7440-36-0	0.000082	0.006575
Iron	7439-89-6	0.000412	0.032875
Beryllium	7440-41-7	0.000008	0.000657
Contains No Reportable TE5081-2 Substances	TE5081-2-0506	0.000007	0.000588
zinc	7440-66-6	0.230894	18.408143
Tin	7440-31-5	0.002823	0.225080
Cobalt	7440-48-4	0.000825	0.065749
Manganese	7439-96-5	0.000412	0.032875
Arsenic	7440-38-2	0.000082	0.006575
Chromium	7440-47-3	0.000008	0.000657
Unspecified Compliant Substance	Unspecified Compliant Substance	0.398240	31.749925
Nickel	7440-02-0	0.005325	0.424565
Gold	7440-57-5	0.001678	0.133784
Copper	7440-50-8	0.589656	47.010705
Cadmium	7440-43-9	0.000082	0.006575
Antimony oxide	1309-64-4	0.023177	1.847801
Mercury	7439-97-6	0.000004	0.000329
Lead	7439-92-1	0.000584	0.046543
<b>All (18 items)</b>			
Total		1.254299	

