

## Tyco Electronics Substance Report

Kumar, Shashi

Dec 18, 2008

The below information is provided based on reasonable inquiry of our suppliers and represents our current actual knowledge based on the information provided by our suppliers. This information is subject to change. This information does not in any way modify existing purchase specifications or existing contractual or other agreement terms between Tyco Electronics Corporation (or its affiliated companies) and its customers.

### General Properties

<b>Part Name</b>	04P MTA156 HDR FLRA FB 30AU LF
<b>Part Number</b>	3-641210-4
<b>Total Part Weight (g)</b>	1.694535
<b>Unit of Measure</b>	EA (each)

### REPORTED CONTENT

<b>Name</b>	<b>CAS Number</b>	<b>Weight (g)</b>	<b>Weight (%)</b>
Mercury	7439-97-6	0.000005	0.000324
Copper	7440-50-8	0.786208	46.396670
Iron	7439-89-6	0.000550	0.032445
Arsenic	7440-38-2	0.000110	0.006489
zinc	7440-66-6	0.307858	18.167703
Nickel	7440-02-0	0.007100	0.419019
Beryllium	7440-41-7	0.000011	0.000649
Manganese	7439-96-5	0.000550	0.032445
Gold	7440-57-5	0.002237	0.132036
Cadmium	7440-43-9	0.000110	0.006489
Lead	7439-92-1	0.000778	0.045936
Contains No Reportable TE5081-2 Substances	TE5081-2-0506	0.000010	0.000580
Cobalt	7440-48-4	0.001100	0.064890
Chromium	7440-47-3	0.000011	0.000649
Unspecified Compliant Substance	Unspecified Compliant Substance	0.551903	32.569541
Tin	7440-31-5	0.003764	0.222140
Antimony oxide	1309-64-4	0.032120	1.895504
Antimony	7440-36-0	0.000110	0.006489
<b>All (18 items)</b>			
Total		1.694535	

