

## Tyco Electronics Substance Report

Kumar, Shashi

Dec 18, 2008

The below information is provided based on reasonable inquiry of our suppliers and represents our current actual knowledge based on the information provided by our suppliers. This information is subject to change. This information does not in any way modify existing purchase specifications or existing contractual or other agreement terms between Tyco Electronics Corporation (or its affiliated companies) and its customers.

### General Properties

<b>Part Name</b>	03P MTA156 HDR ASSY SQ R/A F/L
<b>Part Number</b>	640389-3
<b>Total Part Weight (g)</b>	1.224919
<b>Unit of Measure</b>	EA (each)

### REPORTED CONTENT

<b>Name</b>	<b>CAS Number</b>	<b>Weight (g)</b>	<b>Weight (%)</b>
Unspecified Compliant Substance	Unspecified Compliant Substance	0.398223	32.510115
Arsenic	7440-38-2	0.000079	0.006481
Chromium	7440-47-3	0.000008	0.000648
Beryllium	7440-41-7	0.000008	0.000648
Antimony oxide	1309-64-4	0.023177	1.892123
Cobalt	7440-48-4	0.000794	0.064805
Manganese	7439-96-5	0.000397	0.032403
Copper	7440-50-8	0.567578	46.335890
Contains No Reportable TE5081-2 Substances	TE5081-2-0506	0.000007	0.000600
Nickel	7440-02-0	0.005251	0.428694
Lead	7439-92-1	0.000565	0.046156
Cadmium	7440-43-9	0.000079	0.006481
Antimony	7440-36-0	0.000079	0.006481
zinc	7440-66-6	0.222248	18.143903
Mercury	7439-97-6	0.000004	0.000324
Tin	7440-31-5	0.006025	0.491846
Iron	7439-89-6	0.000397	0.032403
<b>All (17 items)</b>			
Total		1.224919	