

## Tyco Electronics Substance Report

D G, Manjunath  
Dec 15, 2008

The below information is provided based on reasonable inquiry of our suppliers and represents our current actual knowledge based on the information provided by our suppliers. This information is subject to change. This information does not in any way modify existing purchase specifications or existing contractual or other agreement terms between Tyco Electronics Corporation (or its affiliated companies) and its customers.

### General Properties

<b>Part Name</b>	02P MTA156 HDR ASSY RN STR F/L
<b>Part Number</b>	644753-2
<b>Total Part Weight (g)</b>	0.573662
<b>Unit of Measure</b>	EA (each)

### REPORTED CONTENT

<b>Name</b>	<b>CAS Number</b>	<b>Weight (g)</b>	<b>Weight (%)</b>
Chromium	7440-47-3	0.000003	0.000542
Mercury	7439-97-6	0.000002	0.000271
Contains No Reportable TE5081-2 Substances	TE5081-2-0506	0.000003	0.000488
Tin	7440-31-5	0.002378	0.414465
Copper	7440-50-8	0.222422	38.772478
Iron	7439-89-6	0.000156	0.027114
Unspecified Compliant Substance	Unspecified Compliant Substance	0.244566	42.632570
Arsenic	7440-38-2	0.000031	0.005423
Antimony	7440-36-0	0.000031	0.005423
Lead	7439-92-1	0.000222	0.038618
zinc	7440-66-6	0.087095	15.182272
Beryllium	7440-41-7	0.000003	0.000542
Cobalt	7440-48-4	0.000311	0.054227
Manganese	7439-96-5	0.000156	0.027114
Antimony oxide	1309-64-4	0.014234	2.481261
Nickel	7440-02-0	0.002018	0.351769
Cadmium	7440-43-9	0.000031	0.005423

### All (17 items)

Total		0.573662	
-------	--	----------	--