



Basic features

Principle of operation	Mounting bracket for photoelectric sensor
Scope of delivery	Holder Screw M4 Nut Installation guide
Short description	Mounting bracket
Use	for photoelectric sensors BOS 6K

Version

Holder

Material

Material

Die-cast zinc

Mechanical data

Dimension

Ø 32 x 16 mm

Mounting

Screws, clamps