




Basic features

Principle of operation	Mounting bracket for photoelectric sensor
Scope of delivery	Mounting brackets Nut ISO 4032-M4 (2x) Washer ISO 7089-M4 (4x) Screw ISO 1580-M4x25 (2x)
Short description	Mounting bracket
Use	for photoelectric sensors BOS 26K

Version	Mounting brackets 2 adjustable axes
---------	--

Material

Material	Steel
Surface protection	Zinc plated

Mechanical data

Dimension	19 x 48 x 47.6 mm
Mounting	Screws